

Cupola House First-Floor Interior Paint Analysis - *Editor's Note*

Editor's Note: The following report was received by Dr. Susan Buck from her colleagues at The Brooklyn Museum and forwarded at their request to the Cupola House Association. Dr. Buck is the author of *Cupola House Interior and Exterior Paint Analysis*, published on this website. The present report concerns the Cupola House's original first-floor woodwork, which was sold to and installed in The Brooklyn Museum in the early twentieth century. In 2019, Jessica Ford, using up-to-date scientific methodology, re-examined the woodwork paint samples that had been taken in the 1970s from this installation at The Brooklyn Museum. The Cupola House Association is greatly appreciative for The Brooklyn Museum's efforts in discovering and sharing this exciting new information that will enable the true story of the Cupola House to be told more fully. The following report is published courtesy of The Brooklyn Museum and with permission of the Cupola House Association.